

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: ST. JOHN, TOWN OF

Community No: 180141

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMR	05-05-A422P	06/30/2006	LAKE HILLS DEVELOPMENT	1801260080 1801260080B 1801260085 1801260085B 1801410005 1801410005C	18126C0228E 18126C0229E
LOMR	06-05-BA28P	05/29/2007	ST. JOHN MARKETPLACE (MI)	1801410005C	18089C0228E 18089C0229E

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	97-05-2070A	03/20/1997	OAK MEADOWS SUBD. UNIT 3 - LOT 69 - 12699 101ST AVE.	1801410005C	18089C0236E
LOMA	03-05-0586A	02/14/2003	BRAMBLEWOOD UNIT 1, LOTS 19-21, 23-33, 107-110	1801260080B	18126C0210E
LOMA	05-05-4930A	01/12/2006	LAKE HILLS DEVELOPMENT, LOTS 287-289	1801410005C	18089C0229E

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: ST. JOHN, TOWN OF

Community No: 180141

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		